

PRODUCT DISCONTINUATION

#PD-DCT-YFXF-10

Business Unit	Product Line Code	Type of Change	Action	Date of issue
DCT	170	Discontinuation	Notify Distributors and Field	06/24/2010

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

The production of HC-B...ESTC/ HC-B...EBUC and HC-DD...ESTC / HC-DD...EBUC crimp contact carriers will be stopped due to manufacturing reasons. As an alternative, you may now order HC-B...I-CT-M / HC-B...I-CT-F and HC-DD...I-CT-M / HC-DD...I-CT-F contact inserts, found in the new 2009 Pluscon catalog. The alternative articles are identical in construction and thus can replace the discontinued types without any problem. The new inserts also incorporate a tension sleeve principle which provides better tension pull out force than the PE standard screw with pressure plate found in the discontinued products.

Note - This change applies only to the crimp contact carriers, please continue to use the screw connection inserts HC-B...EBUS/ HC-B...ESTS until notified of a discontinuation. Our stock levels and availability on the HC-B...UT-F/ HC-B...UT-M found in the new 2009 Pluscon catalog are very low, so please do not order the new screw connection inserts until notified of improved service levels.

Warranty Information:

N/A

Stock Status

Can existing stock still be used? Y


Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: 06/30/2010

Last Scheduled Ship from Phoenix Contact: 09/30/2010

PRODUCT DISCONTINUATION



Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

NATE OWENS
Pluscon Product Specialist
(717)944-1300x3790
nowens@phoenixcon.com

Thank you,

Dixie Drybread-Erdman

Dixie Drybread- Erdman, Product Marketing Manager

PRODUCT DISCONTINUATION

Discontinued Part#	Type Description	Replacement Part#	Type Description
1771024	HC-B 6-EBUC	1648160	HC-B 6-I-CT-F
1771040	HC-B 6-ESTC	1648157	HC-B 6-I-CT-M
1771215	HC-B 10-EBUC	1648225	HC-B 10-I-CT-F
1771231	HC-B 10-ESTC	1648212	HC-B 10-I-CT-M
1771477	HC-B 16-EBUC	1648283	HC-B 16-I-CT-F
1775635	HC-B 16-EBUC 32	1584923	HC-B 16-I-CT-F-32
1771493	HC-B 16-ESTC	1648270	HC-B 16-I-CT-M
1775648	HC-B 16-ESTC 32	1584910	HC-B 16-I-CT-M-32
1771736	HC-B 24-EBUC	1772117	HC-B 24-EBUC 48
1772117	HC-B 24-EBUC 48	1584981	HC-B 24-I-CT-F-48
1771752	HC-B 24-ESTC	1648335	HC-B 24-I-CT-M
1772120	HC-B 24-ESTC 48	1648335	HC-B 24-I-CT-M
1674655	HC-DD 24-EBUC	1584046	HC-DD 24-I-CT-F
1674668	HC-DD 24-ESTC	1584033	HC-DD 24-I-CT-M
1674671	HC-DD 42-EBUC	1584062	HC-DD 42-I-CT-F
1674684	HC-DD 42-ESTC	1584059	HC-DD 42-I-CT-M
1674697	HC-DD 72-EBUC	1584091	HC-DD 72-I-CT-F
1674736	HC-DD 72-EBUC-144	1584101	HC-DD 72-I-CT-F-144
1674707	HC-DD 72-ESTC	1584075	HC-DD 72-I-CT-M
1674749	HC-DD 72-ESTC-144	1584088	HC-DD 72-I-CT-M-144
1674710	HC-DD 108-EBUC	1584130	HC-DD 108-I-CT-F
1674752	HC-DD 108-EBUC-216	1584143	HC-DD 108-I-CT-F-216
1674723	HC-DD 108-ESTC	1584114	HC-DD 108-I-CT-M
1674765	HC-DD 108-ESTC-216	1584127	HC-DD 108-I-CT-M-216